

			n – I						
OTES: 1. ALL HORIZONTAL MEMBERS ARE MARKED ON "TOP" FACE			E			CLIENT			
OF NORTH OR WEST END			D					$\mathcal{D}$	_
2. * DENOTES MARKS ARE ON THE "TOP" FACE OF SOUTH OR EAST END			C				((	ายก	$) \square$
3. ALL PFC'S , FRAMES , HORIZ/VERT BRACING TO BE								لبلكرح	
ERECTED WITH DIRECTION OF LEGS AS INDICATED ON PLANS OR ELEVATIONS.			в					0	4) <i>(</i> ( )
4. ALL STAIRS ARE MARKED AT TOP END.			A					$\checkmark$	لك ك
5. ALL COLUMNS ARE MARKED ON NORTH OR WEST FLANGE AT BASE END. 6. ALL FIN PLATES ARE ON THE NORTH AND WEST FACE		MARKING PLAN					ACN 11592	21876	
OF CONNECTING BEAM U.O.N		ENGINEERING DWG					DRN	СНК	DATE
	DRG No.	REFERENCE DRAWINGS	REV	DATE	AMENDMENT				