

4.	ALL	STAI RS	ARE	MARKED	AT	TOP	END	ι.				
5.	AL L	COLUMNS	ARF	MARKED	0	I NOR	₹ТН	OR	WEST	FLANGE	AT	I

		D		
		С		
		В		
		Α		
	MARKING PLAN			
	ENGINEERING DWG			
DRG No.	REFERENCE DRAWI NGS	REV	DATE	AMENDMENT

